





THUMB LATCH


www.nationwideindustries.com











Mark and drill where shown then chisel out remaining material from between holes